




# 01 - Kit Components

Everything contained within the GSS-LABEL-PTR-I Industrial Label printer kit.

Written By: Eric Sutter



## INTRODUCTION

Everything contained within the GSS-LABEL-PTR-I Industrial Label printer kit.




The printer should have a metallic silver case on it. If it does not, and instead has an all black case, click [HERE](#).

## Step 1 — Unpacking and Inspection



- A. One printer unit
- B. Four rolls of Direct Transfer labels -OR- 4 rolls of Thermal transfer labels and a roll of ribbon
- C. One ethernet cable
- D. One USB cable
- E. One quick start guide
- F. One power cable.

## Step 2 — Setting up the Printer



- Place the printer on a flat, stable surface.
- Take the plastic film off of the printer, and get the cables out of their packaging.
- Make sure the power switch is off.
- Connect the printer to the computer with the provided USB cable. The square USB-B plug goes into the printer, while the regular USB-A plug should go into your computer.
- Connect an ethernet cable from the printer to your network.
- Plug the power cord into the AC power cord socket at the rear of the printer, and then plug the power cord into a properly grounded power outlet.

## Step 3 — Turning the Printer On



- Flip the power switch to make sure the printer turns on. If it does, the screen should light up and display the EMS logo and phone number.
- Make sure to keep the box and foam inserts. If you need to send the printer back for any reason, you'll need them.